FAA-E-2721/2a October 27, 1983 Superseding FAA-E-2721/2 dated 9/16/82



DEPARTMENT TRANSPORTATION FEDERAL AVIATIONADMINISTRATION **SPECIFICATION**

MICROWAVE LANDING SYSTEM GROUND EQUIPMENT ANGLE GUIDANCE AND DATA

•		


•		

•		

MICROWAVE LANDING SYSTEM GROUND EQUIPMENT

- <u>2-1 SCOPE.</u>- This specification defines the requirements for the Azimuth and Elevation Equipment of the MLS Ground Equipment. This equipment transmits the angle guidance and data functions of the MLS in accordance with the interoperability and performance requirements of FAA-STD-022. Figure 2-1 indicates, in the shaded boxes, the equipment that is covered by this specification.
- <u>2-1.1</u> Equipment interrelationships. The interrelationships of the various equipment and functions of the MLS are specified in FAA-E-2721/1, MLS Ground Equipment, General Requirements. FAA-E-2721/1 also includes the following requirements for all MLS equipment, and accordingly, they are not contained-in this specification:
- (a) General performance requirements such as modularity, electromagnetic compatibility, and maintainability.
- (b) Equipment requirements of a general nature such as common test equipment, power equipment, and Equipment Monitors (EQMs).
- **(c)** General documentation requirements such as reliability, and maintainability plans.'


Figure 2-1. MLS Block Diagram



MICROWAVE LANDING SYSTEM GROUND EQUIPMENT

- <u>2-1 SCOPE.</u>- This specification defines the requirements for the Azimuth and Elevation Equipment of the MLS Ground Equipment. This equipment transmits the angle guidance and data functions of the MLS in accordance with the interoperability and performance requirements of FAA-STD-022. Figure 2-1 indicates, in the shaded boxes, the equipment that is covered by this specification.
- <u>2-1.1</u> Equipment interrelationships. The interrelationships of the various equipment and functions of the MLS are specified in FAA-E-2721/1, MLS Ground Equipment, General Requirements. FAA-E-2721/1 also includes the following requirements for all MLS equipment, and accordingly, they are not contained-in this specification:
- (a) General performance requirements such as modularity, electromagnetic compatibility, and maintainability.
- (b) Equipment requirements of a general nature such as common test equipment, power equipment, and Equipment Monitors (EQMs).
- **(c)** General documentation requirements such as reliability, and maintainability plans.'


Figure 2-1. MLS Block Diagram



MICROWAVE LANDING SYSTEM GROUND EQUIPMENT

- <u>2-1 SCOPE.</u>- This specification defines the requirements for the Azimuth and Elevation Equipment of the MLS Ground Equipment. This equipment transmits the angle guidance and data functions of the MLS in accordance with the interoperability and performance requirements of FAA-STD-022. Figure 2-1 indicates, in the shaded boxes, the equipment that is covered by this specification.
- <u>2-1.1</u> Equipment interrelationships. The interrelationships of the various equipment and functions of the MLS are specified in FAA-E-2721/1, MLS Ground Equipment, General Requirements. FAA-E-2721/1 also includes the following requirements for all MLS equipment, and accordingly, they are not contained-in this specification:
- (a) General performance requirements such as modularity, electromagnetic compatibility, and maintainability.
- (b) Equipment requirements of a general nature such as common test equipment, power equipment, and Equipment Monitors (EQMs).
- **(c)** General documentation requirements such as reliability, and maintainability plans.'


Figure 2-1. MLS Block Diagram



MICROWAVE LANDING SYSTEM GROUND EQUIPMENT

- <u>2-1 SCOPE.</u>- This specification defines the requirements for the Azimuth and Elevation Equipment of the MLS Ground Equipment. This equipment transmits the angle guidance and data functions of the MLS in accordance with the interoperability and performance requirements of FAA-STD-022. Figure 2-1 indicates, in the shaded boxes, the equipment that is covered by this specification.
- <u>2-1.1</u> Equipment interrelationships. The interrelationships of the various equipment and functions of the MLS are specified in FAA-E-2721/1, MLS Ground Equipment, General Requirements. FAA-E-2721/1 also includes the following requirements for all MLS equipment, and accordingly, they are not contained-in this specification:
- (a) General performance requirements such as modularity, electromagnetic compatibility, and maintainability.
- (b) Equipment requirements of a general nature such as common test equipment, power equipment, and Equipment Monitors (EQMs).
- **(c)** General documentation requirements such as reliability, and maintainability plans.'


Figure 2-1. MLS Block Diagram




MICROWAVE LANDING SYSTEM GROUND EQUIPMENT

- <u>2-1 SCOPE.</u>- This specification defines the requirements for the Azimuth and Elevation Equipment of the MLS Ground Equipment. This equipment transmits the angle guidance and data functions of the MLS in accordance with the interoperability and performance requirements of FAA-STD-022. Figure 2-1 indicates, in the shaded boxes, the equipment that is covered by this specification.
- <u>2-1.1</u> Equipment interrelationships. The interrelationships of the various equipment and functions of the MLS are specified in FAA-E-2721/1, MLS Ground Equipment, General Requirements. FAA-E-2721/1 also includes the following requirements for all MLS equipment, and accordingly, they are not contained-in this specification:
- (a) General performance requirements such as modularity, electromagnetic compatibility, and maintainability.
- (b) Equipment requirements of a general nature such as common test equipment, power equipment, and Equipment Monitors (EQMs).
- **(c)** General documentation requirements such as reliability, and maintainability plans.'

Figure 2-1. MLS Block Diagram





NOTE: Dashed contours apply only to antennas providing **±60°** of lateral coverage.

Figure 2-2. Contours of PFE Limits for Azimuth Equipment





Figure 2-3. Contours of PFE Limits For Elevation Equipment



NOTE: Dashed contours apply only to antennas providing **±60°** of lateral coverage.

Figure 2-2. Contours of PFE Limits for Azimuth Equipment





Figure 2-3. Contours of PFE Limits For Elevation Equipment



NOTE: Dashed contours apply only to antennas providing **±60°** of lateral coverage.

Figure 2-2. Contours of PFE Limits for Azimuth Equipment





Figure 2-3. Contours of PFE Limits For Elevation Equipment



NOTE: Dashed contours apply only to antennas providing **±60**° of lateral coverage.

Figure 2-2. Contours of PFE Limits for Azimuth Equipment





Figure 2-3. Contours of PFE Limits For Elevation Equipment



NOTE: Dashed contours apply only to antennas providing **±60**° of lateral coverage.

Figure 2-2. Contours of PFE Limits for Azimuth Equipment





Figure 2-3. Contours of PFE Limits For Elevation Equipment



NOTE: Dashed contours apply only to antennas providing **±60°** of lateral coverage.

Figure 2-2. Contours of PFE Limits for Azimuth Equipment





Figure 2-3. Contours of PFE Limits For Elevation Equipment



NOTE: Dashed contours apply only to antennas providing **±60**° of lateral coverage.

Figure 2-2. Contours of PFE Limits for Azimuth Equipment




Figure 2-3. Contours of PFE Limits For Elevation Equipment

- (a) An integrity alarm initiates an automatic sequence of events to inhibit the **erreoneous** signal radiation and subsequently restore proper operation by . switching to redundant equipment and changing the facility operation& status, if appropriate.
- **(b)** A secondary alert initiates and automatic sequence of events to inhibit the erroneous signal radiation and provide warnings to designated locations.
- **(c)** . A field sensor is one sited remotely from the antenna, with enough sensitivity to detect erroneous signal conditions.
- ,(d) An integral sensor is one that is located within the antenna aperture which samples the radiated signal for monitoring purposes.
- **(e)** Sampling time is the time period used to average samples of a parameter in order to reduce the impact of transients on the monitoring system.
- **(f)** The mean angle error is the result when individual angle measurement errors at a point in space are averaged over a period of time.
- **(g)** An overlap occurs whenever two separate functions (e.g., azimuth and elevation) are radiated simultaneously.
- <u>2-3.5.2 General requirements.</u> The executive monitor shall provide integrity alarms and secondary alerts to the LCSU and EQM and shall be designed such that:
- (a) Conditions that affect performance at any angle within the coverage volume are detected. As a minimum, degradations of the equipment characteristics which contribute to PFE, CMN and angle guidance linearity errors shall be limited as required by FAA-STD-022 and this specification.
- **(b)** Changes in the local (on and/or around the antenna) environment do not cause integrity alarms if the signal-in-space is not degraded out of tolerance.

- (a) An integrity alarm initiates an automatic sequence of events to inhibit the **erreoneous** signal radiation and subsequently restore proper operation by . switching to redundant equipment and changing the facility operation& status, if appropriate.
- **(b)** A secondary alert initiates and automatic sequence of events to inhibit the erroneous signal radiation and provide warnings to designated locations.
- **(c)** . A field sensor is one sited remotely from the antenna, with enough sensitivity to detect erroneous signal conditions.
- ,(d) An integral sensor is one that is located within the antenna aperture which samples the radiated signal for monitoring purposes.
- **(e)** Sampling time is the time period used to average samples of a parameter in order to reduce the impact of transients on the monitoring system.
- **(f)** The mean angle error is the result when individual angle measurement errors at a point in space are averaged over a period of time.
- **(g)** An overlap occurs whenever two separate functions (e.g., azimuth and elevation) are radiated simultaneously.
- <u>2-3.5.2 General requirements.</u> The executive monitor shall provide integrity alarms and -secondary alerts to the LCSU and EQM and shall be designed such that:
- (a) Conditions that affect performance at any angle within the coverage volume are detected. As a minimum, degradations of the equipment characteristics which contribute to PFE, CMN and angle guidance linearity errors shall be limited as required by FAA-STD-022 and this specification.
- **(b)** Changes in the local (on and/or around the antenna) environment do not cause integrity alarms if the signal-in-space is not degraded **out** of tolerance.

- (a) An integrity alarm initiates an automatic sequence of events to inhibit the **erreoneous** signal radiation and subsequently restore proper operation by . switching to redundant equipment and changing the facility operation& status, if appropriate.
- **(b)** A secondary alert initiates and automatic sequence of events to inhibit the erroneous signal radiation and provide warnings to designated locations.
- **(c)** . A field sensor is one sited remotely from the antenna, with enough sensitivity to detect erroneous signal conditions.
- ,(d) An integral sensor is one that is located within the antenna aperture which samples the radiated signal for monitoring purposes.
- **(e)** Sampling time is the time period used to average samples of a parameter in order to reduce the impact of transients on the monitoring system.
- **(f)** The mean angle error is the result when individual angle measurement errors at a point in space are averaged over a period of time.
- **(g)** An overlap occurs whenever two separate functions (e.g., azimuth and elevation) are radiated simultaneously.
- <u>2-3.5.2 General requirements.</u> The executive monitor shall provide integrity alarms and -secondary alerts to the LCSU and EQM and shall be designed such that:
- (a) Conditions that affect performance at any angle within the coverage volume are detected. As a minimum, degradations of the equipment characteristics which contribute to PFE, CMN and angle guidance linearity errors shall be limited as required by FAA-STD-022 and this specification.
- **(b)** Changes in the local (on and/or around the antenna) environment do not cause integrity alarms if the signal-in-space is not degraded **out** of tolerance.

- (a) An integrity alarm initiates an automatic sequence of events to inhibit the **erreoneous** signal radiation and subsequently restore proper operation by . switching to redundant equipment and changing the facility operation& status, if appropriate.
- **(b)** A secondary alert initiates and automatic sequence of events to inhibit the erroneous signal radiation and provide warnings to designated locations.
- **(c)** . A field sensor is one sited remotely from the antenna, with enough sensitivity to detect erroneous signal conditions.
- ,(d) An integral sensor is one that is located within the antenna aperture which samples the radiated signal for monitoring purposes.
- **(e)** Sampling time is the time period used to average samples of a parameter in order to reduce the impact of transients on the monitoring system.
- **(f)** The mean angle error is the result when individual angle measurement errors at a point in space are averaged over a period of time.
- **(g)** An overlap occurs whenever two separate functions (e.g., azimuth and elevation) are radiated simultaneously.
- <u>2-3.5.2 General requirements.</u> The executive monitor shall provide integrity alarms and -secondary alerts to the LCSU and EQM and shall be designed such that:
- (a) Conditions that affect performance at any angle within the coverage volume are detected. As a minimum, degradations of the equipment characteristics which contribute to PFE, CMN and angle guidance linearity errors shall be limited as required by FAA-STD-022 and this specification.
- **(b)** Changes in the local (on and/or around the antenna) environment do not cause integrity alarms if the signal-in-space is not degraded **out** of tolerance.

- (a) An integrity alarm initiates an automatic sequence of events to inhibit the **erreoneous** signal radiation and subsequently restore proper operation by . switching to redundant equipment and changing the facility operation& status, if appropriate.
- **(b)** A secondary alert initiates and automatic sequence of events to inhibit the erroneous signal radiation and provide warnings to designated locations.
- **(c)** . A field sensor is one sited remotely from the antenna, with enough sensitivity to detect erroneous signal conditions.
- ,(d) An integral sensor is one that is located within the antenna aperture which samples the radiated signal for monitoring purposes.
- **(e)** Sampling time is the time period used to average samples of a parameter in order to reduce the impact of transients on the monitoring system.
- **(f)** The mean angle error is the result when individual angle measurement errors at a point in space are averaged over a period of time.
- **(g)** An overlap occurs whenever two separate functions (e.g., azimuth and elevation) are radiated simultaneously.
- <u>2-3.5.2 General requirements.</u> The executive monitor shall provide integrity alarms and -secondary alerts to the LCSU and EQM and shall be designed such that:
- (a) Conditions that affect performance at any angle within the coverage volume are detected. As a minimum, degradations of the equipment characteristics which contribute to PFE, CMN and angle guidance linearity errors shall be limited as required by FAA-STD-022 and this specification.
- **(b)** Changes in the local (on and/or around the antenna) environment do not cause integrity alarms if the signal-in-space is not degraded **out** of tolerance.

- (a) An integrity alarm initiates an automatic sequence of events to inhibit the **erreoneous** signal radiation and subsequently restore proper operation by . switching to redundant equipment and changing the facility operation& status, if appropriate.
- **(b)** A secondary alert initiates and automatic sequence of events to inhibit the erroneous signal radiation and provide warnings to designated locations.
- **(c)** . A field sensor is one sited remotely from the antenna, with enough sensitivity to detect erroneous signal conditions.
- ,(d) An integral sensor is one that is located within the antenna aperture which samples the radiated signal for monitoring purposes.
- **(e)** Sampling time is the time period used to average samples of a parameter in order to reduce the impact of transients on the monitoring system.
- **(f)** The mean angle error is the result when individual angle measurement errors at a point in space are averaged over a period of time.
- **(g)** An overlap occurs whenever two separate functions (e.g., azimuth and elevation) are radiated simultaneously.
- <u>2-3.5.2 General requirements.</u> The executive monitor shall provide integrity alarms and -secondary alerts to the LCSU and EQM and shall be designed such that:
- (a) Conditions that affect performance at any angle within the coverage volume are detected. As a minimum, degradations of the equipment characteristics which contribute to PFE, CMN and angle guidance linearity errors shall be limited as required by FAA-STD-022 and this specification.
- **(b)** Changes in the local (on and/or around the antenna) environment do not cause integrity alarms if the signal-in-space is not degraded **out** of tolerance.

- (a) An integrity alarm initiates an automatic sequence of events to inhibit the **erreoneous** signal radiation and subsequently restore proper operation by . switching to redundant equipment and changing the facility operation& status, if appropriate.
- **(b)** A secondary alert initiates and automatic sequence of events to inhibit the erroneous signal radiation and provide warnings to designated locations.
- **(c)** . A field sensor is one sited remotely from the antenna, with enough sensitivity to detect erroneous signal conditions.
- ,(d) An integral sensor is one that is located within the antenna aperture which samples the radiated signal for monitoring purposes.
- **(e)** Sampling time is the time period used to average samples of a parameter in order to reduce the impact of transients on the monitoring system.
- **(f)** The mean angle error is the result when individual angle measurement errors at a point in space are averaged over a period of time.
- **(g)** An overlap occurs whenever two separate functions (e.g., azimuth and elevation) are radiated simultaneously.
- <u>2-3.5.2 General requirements.</u> The executive monitor shall provide integrity alarms and -secondary alerts to the LCSU and EQM and shall be designed such that:
- (a) Conditions that affect performance at any angle within the coverage volume are detected. As a minimum, degradations of the equipment characteristics which contribute to PFE, CMN and angle guidance linearity errors shall be limited as required by FAA-STD-022 and this specification.
- **(b)** Changes in the local (on and/or around the antenna) environment do not cause integrity alarms if the signal-in-space is not degraded **out** of tolerance.

- <u>2-4.1 General.</u>- The contractor shall provide and maintain a quality control system in accordance with FAA-STD-016, and shall apply the quality assurance provisions as specified in Section 4 of FA-G-2100. The contractor shall also provide and maintain a software quality program in accordance with FAA-STD-01 8. The objective of these quality control systems and programs shall include, but not be limited to, the validation of signal format, rf characteristics, accuracy and coverage requirements as detailed in this specification and in FAA-STD-022. In addition, the contractor shall incorporate in his quality assurance programs the tests described in the paragraphs below and those listed in Table 2-9 or their equivalent unless they are already included in his test program.
- <u>2-4.2 Detailed requirements.</u> The following tests and conditions shall be included in either the design qualification, production or type test plans. Some tests will be required in more than one plan, as specified below. **Table 2-9** summarizes the tests required.
- **2-4.2.1** Test frequencies for design qualification and type tests. The design qualification and type tests under normal test conditions shall be performed at the following five different frequencies: 5031.0 MHz, 5047.8 MHz, 5061.0 MHz, 5075.7 MHz, and 5090.7 MHz. All temperature and humidity tests shall be performed at a frequency of 5061.0 MHz.
- <u>2-4.2.2 Test frequencies for production tests.</u>- All production equipment shall be tested at one of the following three frequencies: 5031.0 MHz, 5061.0 MHz, 5090.7 MHz, as selected by the FAA Quality/Reliability Officer (QRO).
- **2-4.2.3** System factory test range tests.- Measurements shall be performed on a suitable antenna range (either near-field or far-field) to demonstrate the ability of each type of equipment specified in 1-3.1.1 of FAA-E-2721/1 to satisfy the coverage, accuracy and beam shape characteristics required by this specification. Specific tests are detailed below.
- <u>2-4.2.3.1</u> Coverage. Effective radiated power (ERP) shall be demonstrated at least at the nine points indicated by an (x) in Figure 2-4. ERP can be demonstrated by a combination of measured transmitter power (including all interconnect cables losses) and the net antenna gain measured at the points indicated in Figure 2-4.
- <u>2-4.2.3.2</u> Accuracy.- Tests for horizontal coverage accuracy and vertical coverage accuracy shall be as specified in <u>2-4.2.3.2.1</u> and <u>2-4.2.3.2.2</u>. The contractor shall develop the appropriate test procedures to demonstrate compliance with the requirements in a simulated rain condition and over the

- <u>2-4.1 General.</u>- The contractor shall provide and maintain a quality control system in accordance with FAA-STD-016, and shall apply the quality assurance provisions as specified in Section 4 of FA-G-2100. The contractor shall also provide and maintain a software quality program in accordance with FAA-STD-01 8. The objective of these quality control systems and programs shall include, but not be limited to, the validation of signal format, rf characteristics, accuracy and coverage requirements as detailed in this specification and in FAA-STD-022. In addition, the contractor shall incorporate in his quality assurance programs the tests described in the paragraphs below and those listed in Table 2-9 or their equivalent unless they are already included in his test program.
- <u>2-4.2 Detailed requirements.</u> The following tests and conditions shall be included in either the design qualification, production or type test plans. Some tests will be required in more than one plan, as specified below. **Table 2-9** summarizes the tests required.
- **2-4.2.1** Test frequencies for design qualification and type tests. The design qualification and type tests under normal test conditions shall be performed at the following five different frequencies: 5031.0 MHz, 5047.8 MHz, 5061.0 MHz, 5075.7 MHz, and 5090.7 MHz. All temperature and humidity tests shall be performed at a frequency of 5061.0 MHz.
- 2-4.2.2 Test frequencies for production tests.- All production equipment shall be tested at one of the following three frequencies: 5031.0 MHz, 5061.0 MHz, 5090.7 MHz, as selected by the FAA Quality/Reliability Officer (QRO).
- **2-4.2.3** System factory test range tests.- Measurements shall be performed on a suitable antenna range (either near-field or far-field) to demonstrate the ability of each type of equipment specified in 1-3.1.1 of FAA-E-2721/1 to satisfy the coverage, accuracy and beam shape characteristics required by this specification. Specific tests are detailed below.
- <u>2-4.2.3.1</u> Coverage. Effective radiated power (ERP) shall be demonstrated at least at the nine points indicated by an (x) in Figure 2-4. ERP can be demonstrated by a combination of measured transmitter power (including all interconnect cables losses) and the net antenna gain measured at the points indicated in Figure 2-4.
- <u>2-4.2.3.2</u> Accuracy.- Tests for horizontal coverage accuracy and vertical coverage accuracy shall be as specified in <u>2-4.2.3.2.1</u> and <u>2-4.2.3.2.2</u>. The contractor shall develop the appropriate test procedures to demonstrate compliance with the requirements in a simulated rain condition and over the

- <u>2-4.1 General.</u>- The contractor shall provide and maintain a quality control system in accordance with FAA-STD-016, and shall apply the quality assurance provisions as specified in Section 4 of FA-G-2100. The contractor shall also provide and maintain a software quality program in accordance with FAA-STD-01 8. The objective of these quality control systems and programs shall include, but not be limited to, the validation of signal format, rf characteristics, accuracy and coverage requirements as detailed in this specification and in FAA-STD-022. In addition, the contractor shall incorporate in his quality assurance programs the tests described in the paragraphs below and those listed in Table 2-9 or their equivalent unless they are already included in his test program.
- <u>2-4.2 Detailed requirements.</u> The following tests and conditions shall be included in either the design qualification, production or type test plans. Some tests will be required in more than one plan, as specified below. **Table 2-9** summarizes the tests required.
- **2-4.2.1** Test frequencies for design qualification and type tests. The design qualification and type tests under normal test conditions shall be performed at the following five different frequencies: 5031.0 MHz, 5047.8 MHz, 5061.0 MHz, 5075.7 MHz, and 5090.7 MHz. All temperature and humidity tests shall be performed at a frequency of 5061.0 MHz.
- 2-4.2.2 Test frequencies for production tests.- All production equipment shall be tested at one of the following three frequencies: 5031.0 MHz, 5061.0 MHz, 5090.7 MHz, as selected by the FAA Quality/Reliability Officer (QRO).
- **2-4.2.3** System factory test range tests. Measurements shall be performed on a suitable antenna range (either near-field or far-field) to demonstrate the ability of each type of equipment specified in 1-3.1.1 of FAA-E-2721/1 to satisfy the coverage, accuracy and beam shape characteristics required by this specification. Specific tests are detailed below.
- <u>2-4.2.3.1</u> Coverage. Effective radiated power (ERP) shall be demonstrated at least at the nine points indicated by an (x) in Figure 2-4. ERP can be demonstrated by a combination of measured transmitter power (including all interconnect cables losses) and the net antenna gain measured at the points indicated in Figure 2-4.
- <u>2-4.2.3.2</u> Accuracy.- Tests for horizontal coverage accuracy and vertical coverage accuracy shall be as specified in <u>2-4.2.3.2.1</u> and <u>2-4.2.3.2.2</u>. The contractor shall develop the appropriate test procedures to demonstrate compliance with the requirements in a simulated rain condition and over the

- <u>2-4.1 General.</u>- The contractor shall provide and maintain a quality control system in accordance with FAA-STD-016, and shall apply the quality assurance provisions as specified in Section 4 of FA-G-2100. The contractor shall also provide and maintain a software quality program in accordance with FAA-STD-01 8. The objective of these quality control systems and programs shall include, but not be limited to, the validation of signal format, rf characteristics, accuracy and coverage requirements as detailed in this specification and in FAA-STD-022. In addition, the contractor shall incorporate in his quality assurance programs the tests described in the paragraphs below and those listed in Table 2-9 or their equivalent unless they are already included in his test program.
- <u>2-4.2 Detailed requirements.</u> The following tests and conditions shall be included in either the design qualification, production or type test plans. Some tests will be required in more than one plan, as specified below. **Table 2-9** summarizes the tests required.
- **2-4.2.1** Test frequencies for design qualification and type tests. The design qualification and type tests under normal test conditions shall be performed at the following five different frequencies: 5031.0 MHz, 5047.8 MHz, 5061.0 MHz, 5075.7 MHz, and 5090.7 MHz. All temperature and humidity tests shall be performed at a frequency of 5061.0 MHz.
- 2-4.2.2 Test frequencies for production tests.- All production equipment shall be tested at one of the following three frequencies: 5031.0 MHz, 5061.0 MHz, 5090.7 MHz, as selected by the FAA Quality/Reliability Officer (QRO).
- **2-4.2.3** System factory test range tests. Measurements shall be performed on a suitable antenna range (either near-field or far-field) to demonstrate the ability of each type of equipment specified in 1-3.1.1 of FAA-E-2721/1 to satisfy the coverage, accuracy and beam shape characteristics required by this specification. Specific tests are detailed below.
- <u>2-4.2.3.1</u> Coverage. Effective radiated power (ERP) shall be demonstrated at least at the nine points indicated by an (x) in Figure 2-4. ERP can be demonstrated by a combination of measured transmitter power (including all interconnect cables losses) and the net antenna gain measured at the points indicated in Figure 2-4.
- <u>2-4.2.3.2</u> Accuracy.- Tests for horizontal coverage accuracy and vertical coverage accuracy shall be as specified in <u>2-4.2.3.2.1</u> and <u>2-4.2.3.2.2</u>. The contractor shall develop the appropriate test procedures to demonstrate compliance with the requirements in a simulated rain condition and over the

- <u>2-4.1 General.</u>- The contractor shall provide and maintain a quality control system in accordance with FAA-STD-016, and shall apply the quality assurance provisions as specified in Section 4 of FA-G-2100. The contractor shall also provide and maintain a software quality program in accordance with FAA-STD-01 8. The objective of these quality control systems and programs shall include, but not be limited to, the validation of signal format, rf characteristics, accuracy and coverage requirements as detailed in this specification and in FAA-STD-022. In addition, the contractor shall incorporate in his quality assurance programs the tests described in the paragraphs below and those listed in Table 2-9 or their equivalent unless they are already included in his test program.
- <u>2-4.2 Detailed requirements.</u> The following tests and conditions shall be included in either the design qualification, production or type test plans. Some tests will be required in more than one plan, as specified below. **Table 2-9** summarizes the tests required.
- **2-4.2.1** Test frequencies for design qualification and type tests. The design qualification and type tests under normal test conditions shall be performed at the following five different frequencies: 5031.0 MHz, 5047.8 MHz, 5061.0 MHz, 5075.7 MHz, and 5090.7 MHz. All temperature and humidity tests shall be performed at a frequency of 5061.0 MHz.
- 2-4.2.2 Test frequencies for production tests.- All production equipment shall be tested at one of the following three frequencies: 5031.0 MHz, 5061.0 MHz, 5090.7 MHz, as selected by the FAA Quality/Reliability Officer (QRO).
- **2-4.2.3** System factory test range tests. Measurements shall be performed on a suitable antenna range (either near-field or far-field) to demonstrate the ability of each type of equipment specified in 1-3.1.1 of FAA-E-2721/1 to satisfy the coverage, accuracy and beam shape characteristics required by this specification. Specific tests are detailed below.
- <u>2-4.2.3.1</u> Coverage. Effective radiated power (ERP) shall be demonstrated at least at the nine points indicated by an (x) in Figure 2-4. ERP can be demonstrated by a combination of measured transmitter power (including all interconnect cables losses) and the net antenna gain measured at the points indicated in Figure 2-4.
- <u>2-4.2.3.2</u> Accuracy.- Tests for horizontal coverage accuracy and vertical coverage accuracy shall be as specified in <u>2-4.2.3.2.1</u> and <u>2-4.2.3.2.2</u>. The contractor shall develop the appropriate test procedures to demonstrate compliance with the requirements in a simulated rain condition and over the

- <u>2-4.1 General.</u>- The contractor shall provide and maintain a quality control system in accordance with FAA-STD-016, and shall apply the quality assurance provisions as specified in Section 4 of FA-G-2100. The contractor shall also provide and maintain a software quality program in accordance with FAA-STD-01 8. The objective of these quality control systems and programs shall include, but not be limited to, the validation of signal format, rf characteristics, accuracy and coverage requirements as detailed in this specification and in FAA-STD-022. In addition, the contractor shall incorporate in his quality assurance programs the tests described in the paragraphs below and those listed in Table 2-9 or their equivalent unless they are already included in his test program.
- <u>2-4.2 Detailed requirements.</u> The following tests and conditions shall be included in either the design qualification, production or type test plans. Some tests will be required in more than one plan, as specified below. **Table 2-9** summarizes the tests required.
- **2-4.2.1** Test frequencies for design qualification and type tests. The design qualification and type tests under normal test conditions shall be performed at the following five different frequencies: 5031.0 MHz, 5047.8 MHz, 5061.0 MHz, 5075.7 MHz, and 5090.7 MHz. All temperature and humidity tests shall be performed at a frequency of 5061.0 MHz.
- 2-4.2.2 Test frequencies for production tests.- All production equipment shall be tested at one of the following three frequencies: 5031.0 MHz, 5061.0 MHz, 5090.7 MHz, as selected by the FAA Quality/Reliability Officer (QRO).
- **2-4.2.3** System factory test range tests. Measurements shall be performed on a suitable antenna range (either near-field or far-field) to demonstrate the ability of each type of equipment specified in 1-3.1.1 of FAA-E-2721/1 to satisfy the coverage, accuracy and beam shape characteristics required by this specification. Specific tests are detailed below.
- <u>2-4.2.3.1</u> Coverage. Effective radiated power (ERP) shall be demonstrated at least at the nine points indicated by an (x) in Figure 2-4. ERP can be demonstrated by a combination of measured transmitter power (including all interconnect cables losses) and the net antenna gain measured at the points indicated in Figure 2-4.
- <u>2-4.2.3.2</u> Accuracy.- Tests for horizontal coverage accuracy and vertical coverage accuracy shall be as specified in <u>2-4.2.3.2.1</u> and <u>2-4.2.3.2.2</u>. The contractor shall develop the appropriate test procedures to demonstrate compliance with the requirements in a simulated rain condition and over the

- <u>2-4.1 General.</u>- The contractor shall provide and maintain a quality control system in accordance with FAA-STD-016, and shall apply the quality assurance provisions as specified in Section 4 of FA-G-2100. The contractor shall also provide and maintain a software quality program in accordance with FAA-STD-01 8. The objective of these quality control systems and programs shall include, but not be limited to, the validation of signal format, rf characteristics, accuracy and coverage requirements as detailed in this specification and in FAA-STD-022. In addition, the contractor shall incorporate in his quality assurance programs the tests described in the paragraphs below and those listed in Table 2-9 or their equivalent unless they are already included in his test program.
- <u>2-4.2 Detailed requirements.</u> The following tests and conditions shall be included in either the design qualification, production or type test plans. Some tests will be required in more than one plan, as specified below. **Table 2-9** summarizes the tests required.
- **2-4.2.1** Test frequencies for design qualification and type tests. The design qualification and type tests under normal test conditions shall be performed at the following five different frequencies: 5031.0 MHz, 5047.8 MHz, 5061.0 MHz, 5075.7 MHz, and 5090.7 MHz. All temperature and humidity tests shall be performed at a frequency of 5061.0 MHz.
- 2-4.2.2 Test frequencies for production tests.- All production equipment shall be tested at one of the following three frequencies: 5031.0 MHz, 5061.0 MHz, 5090.7 MHz, as selected by the FAA Quality/Reliability Officer (QRO).
- **2-4.2.3** System factory test range tests. Measurements shall be performed on a suitable antenna range (either near-field or far-field) to demonstrate the ability of each type of equipment specified in 1-3.1.1 of FAA-E-2721/1 to satisfy the coverage, accuracy and beam shape characteristics required by this specification. Specific tests are detailed below.
- <u>2-4.2.3.1</u> Coverage. Effective radiated power (ERP) shall be demonstrated at least at the nine points indicated by an (x) in Figure 2-4. ERP can be demonstrated by a combination of measured transmitter power (including all interconnect cables losses) and the net antenna gain measured at the points indicated in Figure 2-4.
- <u>2-4.2.3.2</u> Accuracy.- Tests for horizontal coverage accuracy and vertical coverage accuracy shall be as specified in <u>2-4.2.3.2.1</u> and <u>2-4.2.3.2.2</u>. The contractor shall develop the appropriate test procedures to demonstrate compliance with the requirements in a simulated rain condition and over the

- <u>2-4.1 General.</u>- The contractor shall provide and maintain a quality control system in accordance with FAA-STD-016, and shall apply the quality assurance provisions as specified in Section 4 of FA-G-2100. The contractor shall also provide and maintain a software quality program in accordance with FAA-STD-01 8. The objective of these quality control systems and programs shall include, but not be limited to, the validation of signal format, rf characteristics, accuracy and coverage requirements as detailed in this specification and in FAA-STD-022. In addition, the contractor shall incorporate in his quality assurance programs the tests described in the paragraphs below and those listed in Table 2-9 or their equivalent unless they are already included in his test program.
- <u>2-4.2 Detailed requirements.</u> The following tests and conditions shall be included in either the design qualification, production or type test plans. Some tests will be required in more than one plan, as specified below. **Table 2-9** summarizes the tests required.
- **2-4.2.1** Test frequencies for design qualification and type tests. The design qualification and type tests under normal test conditions shall be performed at the following five different frequencies: 5031.0 MHz, 5047.8 MHz, 5061.0 MHz, 5075.7 MHz, and 5090.7 MHz. All temperature and humidity tests shall be performed at a frequency of 5061.0 MHz.
- 2-4.2.2 Test frequencies for production tests.- All production equipment shall be tested at one of the following three frequencies: 5031.0 MHz, 5061.0 MHz, 5090.7 MHz, as selected by the FAA Quality/Reliability Officer (QRO).
- **2-4.2.3** System factory test range tests. Measurements shall be performed on a suitable antenna range (either near-field or far-field) to demonstrate the ability of each type of equipment specified in 1-3.1.1 of FAA-E-2721/1 to satisfy the coverage, accuracy and beam shape characteristics required by this specification. Specific tests are detailed below.
- <u>2-4.2.3.1</u> Coverage. Effective radiated power (ERP) shall be demonstrated at least at the nine points indicated by an (x) in Figure 2-4. ERP can be demonstrated by a combination of measured transmitter power (including all interconnect cables losses) and the net antenna gain measured at the points indicated in Figure 2-4.
- <u>2-4.2.3.2</u> Accuracy.- Tests for horizontal coverage accuracy and vertical coverage accuracy shall be as specified in <u>2-4.2.3.2.1</u> and <u>2-4.2.3.2.2</u>. The contractor shall develop the appropriate test procedures to demonstrate compliance with the requirements in a simulated rain condition and over the

Table 2-9.	Quality Assurance Test Requirements		3 S / 5	3/2	27/4	3/	TEST CONDITIONS
PARAGRAPH REFERENCES	TITLE	133					TEST CONDITIONS
	c. Pattern shape					•	
	o 2-4.2.4.1.4, 2-4.2.3.3	X					Frequency: 5061 Mhz. Temp: -50°C,+30°+50°C. Elevation angles: +3, +10°, +1 5°
2-3.4.2	5. Azimuth equipment signal	X		х		X	
2-3.4.2.1	6. Azimuth conversion, high rate and normal rate modes		X				
2-3.4.2.2	7. Switchability, Approach azimuth and back azimuth		Х			X	
2-3.4.2.3.1	8. Azimuth/Back Azimuth coverage a. Preamble/Data words ERP	X X		X X		• X X	
	b. Scanning Beam ERP	X		х		X	
	c. Clearance ERP.	X		х		X	
	d. OCI ERP	X		х		X	•
2-3.4.2.3.1	9. Proportional guidance adjustability (AZ)		Х				
2-4.3.2.3.2	10. Clearance guidance (AZ)	χ'		X.		X	
2-3.4.2.3.3	11. Out of coverage indication(AZ)	X		х		X	
2-3.4.2.4.1	12. Data transmissions	X		х		X	
2-3.4.2.4.1	13. Basic data	X		х		X	
						٠	

Table 2-9.	Quality Assurance Test Requirements		3 S / 5	3/2	27/4	3/	TEST CONDITIONS
PARAGRAPH REFERENCES	TITLE	133					TEST CONDITIONS
	c. Pattern shape					•	
	o 2-4.2.4.1.4, 2-4.2.3.3	X					Frequency: 5061 Mhz. Temp: -50°C,+30°+50°C. Elevation angles: +3, +10°, +1 5°
2-3.4.2	5. Azimuth equipment signal	X		х		X	
2-3.4.2.1	6. Azimuth conversion, high rate and normal rate modes		X				
2-3.4.2.2	7. Switchability, Approach azimuth and back azimuth		Х			X	
2-3.4.2.3.1	8. Azimuth/Back Azimuth coverage a. Preamble/Data words ERP	X X		X X		• X X	
	b. Scanning Beam ERP	X		х		X	
	c. Clearance ERP.	X		х		X	
	d. OCI ERP	X		х		X	•
2-3.4.2.3.1	9. Proportional guidance adjustability (AZ)		Х				
2-4.3.2.3.2	10. Clearance guidance (AZ)	χ'		X.		X	
2-3.4.2.3.3	11. Out of coverage indication(AZ)	X		х		X	
2-3.4.2.4.1	12. Data transmissions	X		х		X	
2-3.4.2.4.1	13. Basic data	X		х		X	
						٠	

Table 2-9.	Quality Assurance Test Requirements		3 S / 5	3/2	27/4	3/	TEST CONDITIONS
PARAGRAPH REFERENCES	TITLE	133					TEST CONDITIONS
	c. Pattern shape					•	
	o 2-4.2.4.1.4, 2-4.2.3.3	X					Frequency: 5061 Mhz. Temp: -50°C,+30°+50°C. Elevation angles: +3, +10°, +1 5°
2-3.4.2	5. Azimuth equipment signal	X		х		X	
2-3.4.2.1	6. Azimuth conversion, high rate and normal rate modes		X				
2-3.4.2.2	7. Switchability, Approach azimuth and back azimuth		Х			X	
2-3.4.2.3.1	8. Azimuth/Back Azimuth coverage a. Preamble/Data words ERP	X X		X X		• X X	
	b. Scanning Beam ERP	X		х		X	
	c. Clearance ERP.	X		х		X	
	d. OCI ERP	X		х		X	•
2-3.4.2.3.1	9. Proportional guidance adjustability (AZ)		Х				
2-4.3.2.3.2	10. Clearance guidance (AZ)	χ'		X.		X	
2-3.4.2.3.3	11. Out of coverage indication(AZ)	X		х		X	
2-3.4.2.4.1	12. Data transmissions	X		х		X	
2-3.4.2.4.1	13. Basic data	X		х		X	
						٠	

Table 2-9.	Quality Assurance Test Requirements		3 S / 5	3/2	27/4	3/	TEST CONDITIONS
PARAGRAPH REFERENCES	TITLE	133					TEST CONDITIONS
	c. Pattern shape					•	
	o 2-4.2.4.1.4, 2-4.2.3.3	X					Frequency: 5061 Mhz. Temp: -50°C,+30°+50°C. Elevation angles: +3, +10°, +1 5°
2-3.4.2	5. Azimuth equipment signal	X		х		X	
2-3.4.2.1	6. Azimuth conversion, high rate and normal rate modes		X				
2-3.4.2.2	7. Switchability, Approach azimuth and back azimuth		Х			X	
2-3.4.2.3.1	8. Azimuth/Back Azimuth coverage a. Preamble/Data words ERP	X X		X X		• X X	
	b. Scanning Beam ERP	X		х		X	
	c. Clearance ERP.	X		х		X	
	d. OCI ERP	X		х		X	•
2-3.4.2.3.1	9. Proportional guidance adjustability (AZ)		Х				
2-4.3.2.3.2	10. Clearance guidance (AZ)	χ'		X.		X	
2-3.4.2.3.3	11. Out of coverage indication(AZ)	X		х		X	
2-3.4.2.4.1	12. Data transmissions	X		х		X	
2-3.4.2.4.1	13. Basic data	X		х		X	
						٠	

Table 2-9.	Quality Assurance Test Requirements	<u>/</u>					TEST CONDITIONS
REFERENCES	TITLE	1376				\$\\\ \frac{2}{5}\\\	TEST CONDITIONS
	c. Pattern shape				•		
	o 2-4.2.4.1.4, 2-4.2.3.3	X					Frequency: 5061 Mhz. Temp: -50°C,+30°C+50°C. Elevation angles: +3, +10°, +1 5°
2-3.4.2	5. Azimuth equipment signal	X		х		X	
2-3.4.2.1	6. Azimuth conversion, high rate and normal rate modes		Х				
2-3.4.2.2	7. Switchability, Approach azimuth and back azimuth		Х			X	
2-3.4.2.3.1	8. Azimuth/Back Azimuth coverage a. Preamble/Data words ERP	X X		X X		. X X	·
	b. Scanning Beam ERP	X		х		X	
	c. Clearance ERP.	X		х		X	
	d. OCI ERP	X		х		X	·
2-3.4.2.3.1	9. Proportional guidance adjustability (AZ)		Х				
2-4.3.2.3.2	10. Clearance guidance (AZ)	χ'		X.		X	
2-3.4.2.3.3	11. Out of coverage indication(AZ)	X		х		X	
2-3.4.2.4.1	12. Data transmissions	X		х		X	
2-3.4.2.4.1	13. Basic data	X		х		X	

Table 2-9.	Quality Assurance Test Requirements	<u>/</u>					TEST CONDITIONS
REFERENCES	TITLE	1376				\$\\\ \frac{2}{5}\\\	TEST CONDITIONS
	c. Pattern shape				•		
	o 2-4.2.4.1.4, 2-4.2.3.3	X					Frequency: 5061 Mhz. Temp: -50°C,+30°C+50°C. Elevation angles: +3, +10°, +1 5°
2-3.4.2	5. Azimuth equipment signal	X		х		X	
2-3.4.2.1	6. Azimuth conversion, high rate and normal rate modes		Х				
2-3.4.2.2	7. Switchability, Approach azimuth and back azimuth		Х			X	
2-3.4.2.3.1	8. Azimuth/Back Azimuth coverage a. Preamble/Data words ERP	X X		X X		. X X	·
	b. Scanning Beam ERP	X		х		X	
	c. Clearance ERP.	X		х		X	
	d. OCI ERP	X		х		X	·
2-3.4.2.3.1	9. Proportional guidance adjustability (AZ)		Х				
2-4.3.2.3.2	10. Clearance guidance (AZ)	χ'		X.		X	
2-3.4.2.3.3	11. Out of coverage indication(AZ)	X		х		X	
2-3.4.2.4.1	12. Data transmissions	X		х		X	
2-3.4.2.4.1	13. Basic data	X		х		X	

Table 2-9.	Quality Assurance Test Requirements	<u>/</u>					TEST CONDITIONS
REFERENCES	TITLE	1376				\$\\\ \frac{2}{5}\\\	TEST CONDITIONS
	c. Pattern shape				•		
	o 2-4.2.4.1.4, 2-4.2.3.3	X					Frequency: 5061 Mhz. Temp: -50°C,+30°C+50°C. Elevation angles: +3, +10°, +1 5°
2-3.4.2	5. Azimuth equipment signal	X		х		X	
2-3.4.2.1	6. Azimuth conversion, high rate and normal rate modes		Х				
2-3.4.2.2	7. Switchability, Approach azimuth and back azimuth		Х			X	
2-3.4.2.3.1	8. Azimuth/Back Azimuth coverage a. Preamble/Data words ERP	X X		X X		. X X	·
	b. Scanning Beam ERP	X		х		X	
	c. Clearance ERP.	X		х		X	
	d. OCI ERP	X		х		X	·
2-3.4.2.3.1	9. Proportional guidance adjustability (AZ)		Х				
2-4.3.2.3.2	10. Clearance guidance (AZ)	χ'		X.		X	
2-3.4.2.3.3	11. Out of coverage indication(AZ)	X		х		X	
2-3.4.2.4.1	12. Data transmissions	X		х		X	
2-3.4.2.4.1	13. Basic data	X		х		X	

TABLE OF CONTENTS (CONT'D)

Paragraph	Title	Page
2-3.4.3.1 Coverage 2-3.4.3.2 Out-of-Coverage indication 2-3.4.3.3 Elevation antenna require 2-3.4.3.3.1 Scanning beam antennas 2-3.4.3.3.2 Data (DPSK) antennas 2-3.4.4 Transmitter requirements 2-3.4.4.1 Frequency stabilization 2-3.4.4.2 Tuning 2-3.4.4.3 Maximum output power 2-3.4.4.4 Output power stability 2-3.4.4.5 Output power adjustment 2-3.4.4.6 Output power warm-up 2-3.5 Executive monitor 2-3.5.1 Monitoring terms 2-3.5.2 General requirements 2-3.5.3 Specific requirements 2-3.6.1 Responses to executive monital and status unit 2-3.6.1 Responses to executive monital and status unit 2-3.6.1 Responses to executive monital and status unit 2-3.6.1.1 Integrity alarms 2-3.6.1.1.1 Nonredundant equipments	(LCSU) nitor inputs	10 10 10 12 12 12 12 12 12 13 13 13 14 17 17
2-3.6.1.1.2 Field monitor alarms 2-3.6.1.2 Secondary alerts		17 19
2-3.6.2 Control and display features	S	19
2-4 QUALITY ASSURANCE AND F. 2-4.1 General 2-4.2 Detailed requirements 2-4.2.1 Test frequencies for design 2-4.2.2 Test frequencies for produc 2-4.2.3 System factory test range to 2-4.2.3.1 Coverage 2-4.2.3.2 Accuracy 2-4.2.3.2 Accuracy 2-4.2.3.2.2 Vertical coverage accuracy 2-4.2.3.3 Scanning beam antenna si 2-4.2.3.4 Soft failures 2-4.2.3.5 Radome heat	qualification and type tests etion tests tests curacy test racy test	20 20 20 20 20 20 20 22 22 22 22 23

TABLE OF CONTENTS (CONT'D)

Paragraph	Title	Page
2-3.4.3.1 Coverage 2-3.4.3.2 Out-of-Coverage indication 2-3.4.3.3 Elevation antenna require 2-3.4.3.3.1 Scanning beam antennas 2-3.4.3.3.2 Data (DPSK) antennas 2-3.4.4 Transmitter requirements 2-3.4.4.1 Frequency stabilization 2-3.4.4.2 Tuning 2-3.4.4.3 Maximum output power 2-3.4.4.4 Output power stability 2-3.4.4.5 Output power adjustment 2-3.4.4.6 Output power warm-up 2-3.5 Executive monitor 2-3.5.1 Monitoring terms 2-3.5.2 General requirements 2-3.5.3 Specific requirements 2-3.6.1 Responses to executive monital and status unit 2-3.6.1 Responses to executive monital and status unit 2-3.6.1 Responses to executive monital and status unit 2-3.6.1.1 Integrity alarms 2-3.6.1.1.1 Nonredundant equipments	(LCSU) nitor inputs	10 10 10 12 12 12 12 12 12 13 13 13 14 17 17
2-3.6.1.1.2 Field monitor alarms 2-3.6.1.2 Secondary alerts		17 19
2-3.6.2 Control and display features	S	19
2-4 QUALITY ASSURANCE AND F. 2-4.1 General 2-4.2 Detailed requirements 2-4.2.1 Test frequencies for design 2-4.2.2 Test frequencies for produc 2-4.2.3 System factory test range to 2-4.2.3.1 Coverage 2-4.2.3.2 Accuracy 2-4.2.3.2 Accuracy 2-4.2.3.2.2 Vertical coverage accuracy 2-4.2.3.3 Scanning beam antenna si 2-4.2.3.4 Soft failures 2-4.2.3.5 Radome heat	qualification and type tests etion tests tests curacy test racy test	20 20 20 20 20 20 20 22 22 22 22 23